



1 INSTALLATION



2 INTERFACE CONNECTOR



Quick Start

① INSTALLATION

1. Power Cord
2. RS232 Cable
3. VGA Cable
4. HDMI Cable
5. 3 RCA Component Cable
6. Audio Cable Jack/Jack
7. Audio Cable Jack/RCA
8. Composite Video Cable
9. S-Video Cable

Note: Connector interface is subject to model's specifications

② INTERFACE CONNECTOR

Connecting to a Computer

1. Ensure the projector and your computer are turned off.
2. Connect one end of the VGA cable to the "VGA IN" connector on the projector; connect the other end to the VGA connector on the computer and tighten the screws.
3. Connect one end of the power cord into the AC power socket on the projector; connect the other end to an electrical outlet.

Powering On the Projector

1. Remove the lens cap.
2. Turn on the projector first and then the computer.
3. Adjust the position, focus and zoom.
4. Run you presentation.

Powering Off the Projector

1. Press the power button twice.
2. Do not remove AC power cord from outlet until the projector fan shut down.

クイックスタート

① 接続見本

1. 電源コード
2. RS232 ケーブル
3. VGA ケーブル
4. HDMI ケーブル
5. 3 RCA コンポーネントケーブル
6. オーディオケーブルジャック/ジャック
7. オーディオケーブルジャック/RCA
8. コンポジットビデオケーブル
9. S-Video ケーブル

注意：コネクタインターフェイスは、モデルの仕様によって異なります

② インターフェース（接続端子）

コンピュータとの接続

1. プロジェクタとコンピュータがオフになっていることを確認します。
2. VGA ケーブルをプロジェクタの「VGA IN」コネクタに指し込みます。次にD-SUBケーブルをコンピュータのVGA コネクタに指し込み、ネジをしっかりとし締めます。
3. 電源コードをプロジェクタのAC電源ソケットに指し込み、もう片方をコンセントに指し込みます。

プロジェクタの電源を入れる

1. レンズキャップを外します。
2. 先にプロジェクタの電源をオンにしてから、コンピュータをオンにします。
3. 位置、フォーカス、ズームを調整します。
4. プレゼンテーションを開始します。

プロジェクタの電源を切る

1. 電源ボタンを2回押します。
2. プロジェクタのファンが止まるまで、AC電源コードはコンセントにつないだままにしておいてください。